

WHEELCHAIR LIFT MODELS

CHP 841 (Rev. 1-19) OPI 062

WHEELCHAIR LIFT MODELS Certified by the Manufacturer

In Compliance With Section 34501.1 of the California Vehicle Code

Commercial Vehicle Section (CVS) has received information from the following manufacturers certifying the indicated wheelchair lift models comply with requirements contained in Title 13, California Code of Regulations, as required by Section 34501.1 of the California Vehicle Code:

Manufacturer: All American Transit Parts
Lift Model Numbers

| | | | |
|----------|----------|-----------|----------|
| AATP 124 | AATP 125 | AATP 130 | AATP 140 |
| AATP 141 | AATP 142 | AATP 145 | AATP 147 |
| AATP 148 | AATP 153 | AATP 2000 | |

Manufacturer: Boswell Machine Inc.
Lift Model Numbers

Safe-T-Product Lift 1926P

Manufacturer: Braun Corp.
Lift Model Numbers

| | | | |
|--------------|--------------|-------------|-------------|
| L-10U | L-10U44 | L-10U50 | L-10U52 |
| L-10U54 | L-10UTC | L-11U | L-11U64 |
| L-18C | L-18D | L-18F | L-19C |
| L-19CADA | L-19D | L-19DADA | L-19F |
| L-19FADA | L-20U | L-21U | L-21U58 |
| L-21U64 | L-21U67 | L-21U68 | L-21U70 |
| L-23U | L-25U | L-25U64 | L-26U |
| L-27U67 | L-28U | L-28U64 | L-28U67 |
| L-40U | L-41U | L-41U64 | L-42U |
| L-100U | L-100U44 | L-100U50 | L-100U52 |
| L-100U54 | L-100U64 | L-101U | L-127U |
| L-127U58 | L-127U62 | L-127U64 | L-200U |
| L-201U | L-203X | L-205U | L-205U64 |
| L-206U | L-207U67 | L-208U | L-208U64 |
| L-208U64PB | L-208U67 | L-209U64 | L-210U64 |
| L-211U58 | L-211U64 | L-211U67 | L-211U68 |
| L-211U70 | L-220U | L-400U | L-400USE |
| L-401U | L-401USE | L-402U | L-402USE |
| L-2050 | L-2050TC | L-2060 | L-2080 |
| L-205064 | L900F | L900FARS | L900FARSTC |
| L900R | L900R2944 | L900R3050ME | L900R3150ME |
| L900RARS | L900RARS3041 | L900U | L901F |
| L901FARS | L901R | L901U | L902F |
| L902FARS | L902R | L902RARS | L902RARS24V |
| L902RARS3044 | L902RARSWV | L903R | L903RARS |



**Manufacturer:
Lift Model Numbers**

Braun Corp.

| | | | |
|------------------|-------------------|-------------------|-------------------|
| L903RARS24V | L904R | L904RARS | L904RARS3653 |
| L911FARS | L911FARS3548 | L911FARS3550 | L911FARSIB |
| L911FARSIBCC | L911RARS | L911RARS3348 | L911RARS3451 |
| L911RARS3548 | L911RARS3550 | L911RARS3648 | L911RARSCC |
| L911RARSFDOT | L911RARSHMET | L911RARSIB | L911RARSIBA |
| L911RARSIBCC | L911RARSIBK | L911RIB3550 | L911RIB3750 |
| L911RIB3750A | L911RIBHMET | L911RIBNJT | L911U |
| L911U02 | L912FARS | L912RARS | L912RARS3148 |
| L912RARS3348 | L912RARSIB | L912RARSIBA | L912RARSWV |
| L913FARS | L913FARSIB | L913FARSIBA | L913FARSIBME |
| L913RARS | L913RARSFDOT | L913RARSIB | L913RARSIBA |
| L913RARSMASS | L914FARS | L914FARSIB | L914FARSMASS |
| L914RARS | L914RARSIB | L914RARSMM | L915 |
| L915F | L915FIB | L915FIBTC | L915IB |
| L915IBTC | L915RARS | L915RARSA | L916 |
| L916F | L916FIB | L916FIB3250 | L916FIB3250TB |
| L916IB | L917 | L917F | L917FIB |
| L917FIB3454 | L917FIB3454RP-2 | L917FIB3454RP-2AA | L917FIB3454YF |
| L917FIB3550 | L917FIB3550AB | L917FIB3750 | L917FIB3750HBTL |
| L917FIB3751RP-2 | L917FIB3751RP-2AA | L917FIBHB | L917FIBHMET |
| L917FIBHMETHB | L917FIBM | L917FIBME | L917FIBMM |
| L917FIBPACE | L917FIBRP | L917FIBTC | L917FNJT |
| L917IB | L917IB-2 | L917IB3454 | L917IB3454HB |
| L917IB3454RP-2 | L917IB3454RP-2AA | L917IB3550 | L917IB3659 |
| L917IB3750 | L917IB3750HB | L917IB3750HBTL | L917IB3750TL |
| L917IB3751RP-2 | L917IB3751RP-2AA | L917IBHB | L917IBHBTL |
| L917IBHMET | L917IBHMETHB | L917IBME | L917IBMM |
| L917IBPACE | L917IBPACEHB | L917IBRP | L917IBTL |
| L917NJT | L918 | L9183343TYT | L918F |
| L918FIB | L918FIB3343 | L918FIB3343TC | L918FIBHRB |
| L918FIBLT | L918FIBMASS | L918FIBOT | L918FIBTC |
| L918IB | L918IB3342RP-2TC | L918IB3343 | L918IB3343RP-2TC |
| L918IB3343TC | L918IB3343TYT | L918IB3351RP-2TC | L918IB3354 |
| L918IB3354LT | L918IB3354TC | L918IB3443RP-2 | L918IB3443RP-2AA |
| L918IB3443RP-2TC | L918IBAB | L918IBHRB | L918IBMASS |
| L918IBTC | L919 | L919BCT | L919F |
| L919FIB | L919FIBHB | L919FIBHBPT | L919FIBMM |
| L919FIBRP-2 | L919FIBRP-2AA | L919IB | L919IBCT |
| L919IBHB | L919IBMM | L919IBRP-2 | L919IBRP-2AA |
| L919IBRP-2TC | L921FARS | L921FARSIB | L923FARS |
| L923RARS | L923RIBC3244 | L924IBC3242 | L924RARS |
| L924RIBC | L924RIBC3242 | L924RIBC3243 | L924RIBC3243TYT |
| L924RIBC3244 | L924RIBCTYT | L925 | L925F |
| L925FIB | L925FIBTC | L925FIBTYT | L925IB |
| L925IBTC | L926 | L926F | L926FIB |
| L926IB | L927 | L927F | L927FIB |
| L927FIB3454RP-2 | L927FIB3454RP-2AA | L927FIB3751RP-2 | L927FIB3751RP-2AA |
| L927FIBTC | L927IB | L927IB3454RP-2 | L927IB3454RP-2AA |



**Manufacturer:
Lift Model Numbers**

Braun Corp.

| | | | |
|--------------------|--------------------|--------------------|--------------------|
| L927IB3751RP-2 | L927IB3751RP-2AA | L928 | L928F |
| L928FIB | L928FIB3343 | L928FIB3343TC | L928FIB3343TYT |
| L928FIBHRB | L928FIBTC | L928FIBTYT | L928IB |
| L928IB3343 | L928IB3343TYT | L928IB3351RP-2TC | L928IBHRB |
| L928IBTC | L928IBTYT | L929 | L929F |
| L929FIB | L929FIBRP-2 | L929FIBRP-2AA | L929FIBRP-2TC |
| L929IB | L929IBRP-2 | L929IBRP-2AA | L929IBRP-2TC |
| L932RARSIBA | L932RARSIBB | L933FARSIBA | L933RARSIBA |
| L934FARSIBA | L934RARSIB | L934RARSIBA | L937 |
| L937F | L937FIB | L937IB | L937IBSDU |
| L950R2943 | L950R2945 | L950R2947 | L950R2949 |
| L950R2950 | L950R3347 | L950R3350 | L950R3547 |
| L950SE294248 | L950SE294248TC | L950SE294652 | L950SE295056 |
| L950SE2951 | L950SE304652 | L950SE305056 | L950SE314652 |
| L950SE334248 | L950SE334652 | L950U294248 | L950U294551 |
| L950U294652 | L950U295056 | L950U295460 | L950U295561 |
| L950U304248 | L950U304652 | L950U305056 | L950U314248 |
| L950U324248 | L950U324652 | L950U344248 | L950U345056 |
| L950U345460 | L950U354248 | L950U354248M | L950U355056 |
| L950U364248 | L950U365056 | L951R2950 | L951U294248 |
| L951U295056 | L952SE2740IB-2 | L952SE2740IB-2AA | L955SE314248 |
| L955SE314248-24V | L955SE314248HRB | L955SE314248L | L955SE314248TC |
| L955SE3143IB | L955SE3143IB-2 | L955SE3143IB-2AA | L955SE314652 |
| L955SE314652L | L955SE3147IB | L955SE315056 | L955SE3151IB |
| L955SE345460 | L955SE3455IB | L955SE3455IB-2 | L955SE3455IB-2AA |
| L955U314248 | L955U314652 | L955U315056 | L960U295056 |
| L990IB | L990IB2740-2 | L990IB2740-2AA | L990RARS |
| L990RARSHRB | L990RARSTC | L990RARSTYT | L990U |
| NCL1000FIB3351-2 | NCL1000FIB3451-2 | NCL1000FIB3451HB-2 | NCL1000FIB3454-2 |
| NCL1000FIB3454HB-2 | NCL1000FIB3454RP-2 | NCL1000FIB37512 | NCL1000FIB3751HB-2 |
| NCL1000FIB3754-2 | NCL1000FIB3754HB-2 | NCL1000IB3351-2 | NCL1000IB3451-2 |
| NCL1000IB3451HB-2 | NCL1000IB3454-2 | NCL1000IB3454HB-2 | NCL1000IB3751-2 |
| NCL1000IB3751HB-2 | NCL1000IB3754-2 | NCL1000IB3754HB-2 | NCL917FIB |
| NCL917FIB-2 | NCL917FIB3354-2 | NCL917FIB3354HB-2 | NCL917FIB3454-2 |
| NCL917FIB3454HB-2 | NCL917FIB3454RP-2 | NCL917FIBHB | NCL917FIBHBY-2 |
| NCL917FIBMM | NCL917FIBRP | NCL917FIBRP-2 | NCL917FIBRP3354-2 |
| NCL917FIBRPHB-2 | NCL917FIBRPLT-2 | NCL917FIBTB-2 | NCL917FIBYP-2 |
| NCL917IB | NCL917IB-2 | NCL917IB3354-2 | NCL917IB3454-2 |
| NCL917IB3454HB-2 | NCL917IBHB-2 | NCL917IBHBY-2 | NCL917IBLT-2 |
| NCL917IBMM | NCL917IBOHB-2 | NCL917IBTB | NCL917IBTB-2 |
| NCL917IBYP-2 | NCL919FIB | NCL919FIB-2 | NCL919FIBFHB-2 |
| NCL919FIBHB | NCL919FIBHB-2 | NCL919FIBHBY-2 | NCL919FIBIC-2 |
| NCL919FIBMM | NCL919FIBRP-2 | NCL919FIBTB | NCL919FIBTB-2 |
| NCL919FIBYP-2 | NCL919IB | NCL919IB-2 | NCL919IBFHP-2 |
| NCL919IBHB | NCL919IBHB-2 | NCL919IBHBY-2 | NCL919IBIC-2 |
| NCL919IBMM | NCL919IBRP-2 | L928FIB | L928FIB3343 |



**Manufacturer:
Lift Model Numbers**

Braun Corp.

| | | | |
|------------------|------------------|------------------|-------------------|
| NCL919IBTB | NCL919IBTB-2 | NCL954FIB3454-2 | NCL954FIB3454HB-2 |
| NCL954IB3454-2 | NCL954IB3454HB-2 | NCL955IB3143EK-2 | NCL955IB3143-2 |
| NCL999IB-2 | NDCC54S34x54L | NDCC54S34x54LHB | NDCC54S34x54R |
| NDCC54S34x54RHB | NL500 | NL500-24 | NL500M24 |
| NL501-24 | NL502-24 | NL503-24 | NL915FIB |
| NL915IB | NL916FIB | NL916FIB-2 | NL916FIBRP |
| NL916FIBRP-2 | NL916IB | NL916IB-2 | NL917FIB |
| NL917FIB-2 | NL917FIB-QD | NL917FIB3354 | NL917FIB3354HB |
| NL917FIB3354HB-2 | NL917FIB3454 | NL917FIB3454-2 | NL917FIB3454HB-2 |
| NL917FIB3551 | NL917FIB3551-2 | NL917FIB3751 | NL917FIB3751-2 |
| NL917FIB3751HB-2 | NL917FIBHB | NL917FIBHB-2 | NL917FIBLT-2 |
| NL917FIBMM | NL917FIBRP | NL917FIBRP-2 | NL917FIBRPHB |
| NL917FIBRPHB-2 | NL917FIBTB | NL917FIBTB-2 | NL917IB |
| NL917IB-2 | NL917IB3354 | NL917IB3354HB | NL917IB3454 |
| NL917IB3454-2 | NL917IB3551 | NL917IB3751 | NL917IB3751-2 |
| NL917IBHB | NL917IBHB-2 | NL917IBLT-2 | NL917IBLTP-2 |
| NL917IBMM | NL917IBRP | NL917IBTB | NL917IBTB-2 |
| NL917IBTBYP-2 | NL917IBYP-2 | NL918FIB | NL918FIB3343PN |
| NL918IB | NL918IB3343P | NL919FIB | NL919FIB-2 |
| NL919FIBHB | NL919FIBHB-2 | NL919FIBHB-QD | NL919FIBHBPT |
| NL919FIBHBPT-2 | NL919FIBIC-2 | NL919FIBMM | NL919FIBRP-2 |
| NL919FIBTB | NL919FIBTB-2 | NL919FIBYP-2 | NL919IB |
| NL919IB-2 | NL919IBHB | NL919IBHB-2 | NL919IBIC-2 |
| NL919IBMM | NL919IBRP-2 | NL919IBTB | NL919IBTB-2 |
| NL919IBYP-2 | NL955IB3143-2 | NL955IB3147-2 | NL955IB3151-2 |
| NL955M33545ITB | NL955SE3143 | NL955SE3143IB-2 | NL955SE3143IBEK-2 |
| NL955SE3143MM | NL955SE3147 | NL955SE3147IB-2 | NL955SE3147IBEK-2 |
| NL955SE3147MM | NL955SE3151 | NL955SE3151IB-2 | NL955SE3151IBEK-2 |
| NL955SE3151MM | NUVL603C | NUVL604XA | NUVL604XB |
| NUVL855C | NUVL855CFST | NUVL855ESM | NUVL855R |
| NUVL855RM24 | NUVL855SM | NUVL855SMXB | NUVL865 |
| NUVL865-24V | NV05FSL | NV05FSW | NV05SSL |
| NV05SSW | NVL917FIB | NVL917FIB-2 | NVL917FIBHB |
| NVL917FIBHB-2 | NVL917FIBMM | NVL917FIBRP | NVL917FIBTB |
| NVL917FIBTB-2 | NVL917IB | NVL917IB-2 | NVL917IBHB |
| NVL917IBHB-2 | NVL917IBLT-2 | NVL917IBMM | NVL917IBTB |
| NVL917IBTB-2 | NVL919FIB-2 | NVL919FIBHB-2 | NVL919FIBRP-2 |
| NVL919IB-2 | NVL919IBHB-2 | NVL919IBRP-2 | NVL920FIB |
| NVL920IB | NVL955IB3144MM | NVL955IB3144 | UFL1000 |
| UFL1000TT | UFL1001 | UVL601A | UVL601C |
| UVL601C-AA | UVL603A | UVL603B | UVL603B24 |
| UVL603C | UVL603C24 | UVL603C-AA | UVL603E |
| UVL604XA | UVL604XA24 | UVL604XB | UVL604XB24 |
| UVL604XB FED | UVL604XC | UVL604XD | UVL606 |
| UVL606A | UVL606A24 | UVL855CFRWB | UVL855CFS |
| UVL855CFST | UVL855CFSTR | UVL855E | UVL855EM |
| UVL855ESM | UVL855EVO | UVL855EVOM | UVL855GK |



**Manufacturer:
Lift Model Numbers**

Braun Corp.

| | | | |
|---------------|-----------|--------------|------------|
| UVL855IRS | UVL855M | UVL855M24 | UVL855NOGE |
| UVL855R | UVL855R24 | UVL855R24-AA | UVL855R-AA |
| UVL855RFW | UVL855RH | UVL855S | UVL855SM |
| UVL855SM24 | UVL855SMT | UVL855SMXB | UVL855STEP |
| UVL855STEP-AA | UVL855TR | UVL855TT | UVL2000XT |
| UVL2000XT24 | | | |

**Manufacturer:
Lift Model Numbers**

Collins Mobile-Tech Corp.

| | | | |
|-----------------|-------------------|--------------------|--------------------|
| Step Lift 3200 | Step Lift 3231 | Step Lift 3232 | Step Lift 3233 |
| Step Lift 32350 | Step Lift 32400 | Step Lift 32-4231 | Step Lift 32-4232 |
| Step Lift S3230 | Step Lift 32-4233 | Step Lift 32-42350 | Step Lift 32-42400 |

**Manufacturer:
Lift Model Number**

Environmental Equipment Corp.

2000

**Manufacturer:
Lift Model Number**

Hidral Gobel

300/BP

**Manufacturer:
Lift Model Numbers**

Lift-U

| | | | |
|--------------|--------------|--------------|------------------------|
| 1081 | 1145 | 1147 | 1149 |
| 1153 and up* | 3078 | 3086 and up* | 6012 and up* |
| 9048-9053 | 9055 and up* | B012 and up* | L025 and up* |
| LU0 | LU10 | LU12 | LU2-05-01 (LU2-xx-xx)* |
| LU3-14-01 | LU-III | R003 and up* | T001 |
| W001 | | | |

**Manufacturer:
Lift Model Number**

Maxon Lift Corp.

| | |
|-------|-------|
| WL-6A | WL-7A |
|-------|-------|

**Manufacturer:
Lift Model Number**

Metro Trans Hide N Lift

Metro Trans Hide N Lift

**Manufacturer:
Lift Model Number**

REB Manufacturing Co., Inc.

Z-335



**Manufacturer:
Lift Model Numbers**

Ricon Inc.

| | | | |
|----------------------|----------------------|----------------------|----------------------|
| F9A-A001 to F9A-A009 | F9A-A011 to F9A-A019 | F9A-A022 | F9A-A023 |
| F9A-A025 to F9A-A029 | F9A-A029SP | F9A-A030 | F9A-A033 to F9A-A035 |
| F9A-S000 | F9A-S002 to F9A-S005 | F9A-S007 to F9A-S014 | F9A-S016 to F9A-S032 |
| F9T-DE001 | F9TF-DE001 | F9TF-DE002 | F9TF-DE003 |
| F9TF-DE004 | F9TF-DE006 | F9TF-DE007 | F9TF-DE009 |
| F9TF-DE011 | F9TF-DE012 | F9TF-DE015 | F9TF-DE027 |
| F9TF-DS001 | F9TF-SG001 | F9TF-SG002 | F9TF-SG003 |
| F9TF-SG006 | F9TF-SG007 | F9TF-SG008 | F9TF-SG009 |
| F9TF-SG016 | F9TH-DE035 | F9TH-DE038 | F9000 |
| F9000SW | F9003 | F9003MC | K2003-F1020000A |
| K2003-T | K2005-F1020000A | K2005-F1020000B | K2005-F1020000C |
| K2005-F1020100A | K2005-F1020100B | K2005-F1020100C | K2005-F1020300A |
| K2005-T | K2010-F102000A | K2010-F1020000A | K2010-F1020000B |
| K2010-F1020000C | K2010-F1020100A | K2010-F1020100B | K2010-F1020100C |
| K2010-F1020200A | K2010-F1020300A | K2010-F1020300C | K2010-F10201002 |
| K5000-F1020100A | K5003-T | K5005-F1020000A | K5005-F1020100A |
| K5005-F1020100B | K5005-S | K5005-S1000000 | K5005-T |
| K5503-F | K5503-F120000A | K5503-F120100A | K5503-F1200000A |
| K5503-F1201000A | K5505-F | K5505-F1020000A | K5505-F1020000B |
| K5505-F1020000C | K5505-F1020100A | K5505-F1020100B | K5505-F1200100A |
| K5505-F1200100B | K5505-F1200100C | K5505-L1120501H | K5510-F |
| K5510-F1020000A | K5510-F1020000B | K5510-F1020000C | K5510-F1020100A |
| K5510-F1020100B | K5510-F1020100C | K5510-F1020100K | RIF9TF-DE001 |
| RIF9TF-DE002 | RIF9TF-DE003 | RIF9TF-DE004 | RIF9TF-DE006 |
| RIF9TF-DE007 | RIF9TF-DE009 | RIF9TF-DE011 | RIF9TF-DE012 |
| RIF9TF-DE022 | RIF9TF-DS001 | RIF9TF-SG001 | RIF9TF-SG002 |
| RIF9TF-SG003 | RIF9TF-SG006 | RIF9TF-SG007 | RIF9TF-SG008 |
| RIF9TF-SG009 | RIF9TF-SG016 | RIF9TH-DE035 | RIF9TH-DE038 |
| RIF10XF-0001 | RIF10XF-0002 | RIK2003-F1020000A | RIK2005-C1020000D |
| RIK2005-C1020100D | RIK2005-C1120601N | RIK2005-C1120701N | RIK2005-F1020000A |
| RIK2005-F1020000B | RIK2005-F1020000C | RIK2005-F1020100A | RIK2005-F1020100B |
| RIK2005-F1020100C | RIK2005-F1020300A | RIK2005FF1120601N | RIK2005FF1120701N |
| RIK2010-C1020000D | RIK2010-C1020100D | RIK2010-C1120601N | RIK2010-C1120701N |
| RIK2010-F1020000A | RIK2010-F1020000B | RIK2010-F1020000C | RIK2010-F1020100A |
| RIK2010-F1020100B | RIK2010-F1020200A | RIK2010-F1020300A | RIK2010-F1020300C |
| RIK2010-F10201002 | RIK2010FF1120601N | RIK5000-F1020100A | RIK5005-F1020000A |
| RIK5005-F1020100A | RIK5005-F1020100B | RIK5503-F1200000A | RIK5503-F1201000A |
| RIK5505-C1020100D | RIK5505-C1120601N | RIK5505-C1120701N | RIK5505-F1020000A |
| RIK5505-F1020000B | RIK5505-F1020000C | RIK5505-F1020100A | RIK5505-F1020100B |
| RIK5505-F1200100A | RIK5505-F1200100B | RIK5505-F1200100C | RIK5505FF1120601N |
| RIK5505FF1120701N | RIK5510-C1020100D | RIK5510-C1120601N | RIK5510-C1120701N |
| RIK5510-F1020000A | RIK5510-F1020000B | RIK5510-F1020000C | RIK5510-F1020100A |
| RIK5510-F1020100B | RIK5510-F1020100C | RIK5510-F1020100K | RIK5510FF1120601E |
| RIK5510FF1120601N | RIK5510FF1120701E | RIK5510FF1120701N | RIS2003-F1020000A |
| RIS2003-F1020000B | RIS2003-F1020100A | RIS2005-C1020000D | RIS2005-C1020100D |



**Manufacturer:
Lift Model Numbers**

Ricon Inc.

| | | | |
|-------------------|-------------------|-------------------|-------------------|
| RIS2005-C1120601N | RIS2005-C1120701N | RIS2005-F1020000A | RIS2005-F1020000B |
| RIS2005-F1020000C | RIS2005-F1020100A | RIS2005-F1020100C | RIS2005-F1020200A |
| RIS2005-F1020300A | RIS2005-F1020300B | RIS2005-F1021000B | RIS2005FF1120601N |
| RIS2005FF1120701N | RIS2006-F1020000A | RIS2006-F1020100A | RIS2010-C1020100D |
| RIS2010-C1120601N | RIS2010-C1120701N | RIS2010-F1020000A | RIS2010-F1020000B |
| RIS2010-F1020000C | RIS2010-F1020100A | RIS2010-F1020100B | RIS2010-F1020100C |
| RIS2010-F1020300A | RIS2010-F1020300C | RIS2010FF1120601E | RIS2010FF1120601N |
| RIS2010FF1120701E | RIS2010FF1120701N | RIS2036-F1020000A | RIS2036-F1020200A |
| RIS5005-F1020000A | RIS5005-F1020100A | RIS5503-F1020000A | RIS5503-F1020000C |
| RIS5503-F1020100A | RIS5503-F1020100B | RIS5505-C1020000D | RIS5505-C1020100D |
| RIS5505-C1120601N | RIS5505-C1120701N | RIS5505-F1020000A | RIS5505-F1020000B |
| RIS5505-F1020000C | RIS5505-F1020100A | RIS5505-F1020100B | RIS5505-F1020300A |
| RIS5505-F1020300C | RIS5505FF1120601N | RIS5505FF1120701N | RIS5510-C1020000D |
| RIS5510-C1020100D | RIS5510-C1120601N | RIS5510-C1120701N | RIS5510-F1020000A |
| RIS5510-F1020000B | RIS5510-F1020000C | RIS5510-F1020100A | RIS5510-F1020100B |
| RIS5510-F1020100C | RIS5510-F1020300A | RIS5510-F1020300B | RIS5510FF1120601E |
| RIS5510FF1120601N | RIS5510FF1120701E | RIS5510FF1120701N | RISSBF3759-1 |
| RISSBF3759-1R | RISSBF3759-3 | RISSBF3761-1 | RISSBF3761-2 |
| RISSBF3761-3 | RISSBF3761-3R | RISSBF3761-4 | S2000 |
| S2003-F1020000A | S2003-F1020000B | S2003-F1020100A | S2003-S10000000 |
| S2004 | S2005 | S2005-F1020000A | S2005-F1020000B |
| S2005-F1020000C | S2005-F1020100A | S2005-F1020100C | S2005-F1020200A |
| S2005-F1020300A | S2005-F1020300B | S2005-F1021000B | S2005-L1120401H |
| S2005-L1120501H | S2005-S10001003 | S2006-F1020000A | S2006-F1020100A |
| S2007 | S2008 | S2010-F1020000A | S2010-F1020000B |
| S2010-F1020000C | S2010-F1020100A | S2010-F1020100B | S2010-F1020100C |
| S2010-F1020300A | S2010-F1020300C | S2010-L1120501H | S2036-F1020000A |
| S2036-F1020200A | S5000 | S5003 | S5003-S1000000 |
| S5004 | S5005-F1020100A | S5007 | S5008 |
| S5503-F1020000A | S5503-F1020000C | S5503-F1020100A | S5503-F1020100B |
| S5505-F | S5505-F1020000A | S5505-F1020000B | S5505-F1020000C |
| S5505-F1020100A | S5505-F1020100B | S5505-F1020300A | S5505-F1020300C |
| S5505-L1120501H | S5510-F | S5510-F1020000A | S5510-F1020000B |
| S5510-F1020000C | S5510-F1020100A | S5510-F1020100B | S5510-F1020100C |
| S5510-F1020300A | S5510-F1020300B | S5510-L1120501H | SSBF3759-1 |
| SSBF3759-1R | SSBF3759-3 | SSBF3761-1 | SSBF3761-2 |
| SSBF3761-3 | SSBF3761-3R | SSBF3761-4 | |

**Manufacturer:
Lift Model Numbers**

Stewart and Stevenson Power

| | | | |
|-------------|-------------|-------------|-------------|
| SSBL3354-1 | SSBL3759-1 | SSBL3761-1 | SSBL3761-2 |
| SSBL3761-4 | SSPL-380 | SSPL-510 LA | SSPL-510 RA |
| SSPL-550 LA | SSPL-550 RA | | |



Manufacturer:
Lift Model Number

Transportation Mfg. Corp. (TMC)

T80206

Manufacturer:
Lift Model Number

Wide One Corporation

Lectralift Model 6000

As the Department receives certification documentation and test data for other makes and models of wheelchair lifts, this list will be updated and published. Questions regarding this matter should be directed to CVS, at (916) 843-3400.

*Note: In the past, the Department accepted certification data for some model numbers listed "XXXX and up." However, field personnel may have difficulty in determining which specific model numbers have been certified and which have not. Consequently, all future certifications shall include the specific model number(s) to which the certification applies. No "open ended" model numbers will be permitted.

